Site Name: Task Order 62 CES Environmental Branch: Federal		Operational Period: Date: 3-9-2015 Division/ Group: Response			U.S. EPA Region 6 DAILY WORK ORDER mergency and Rapid Response Service				
									WORK AUTHORIZED:
Continue to pump water on si									
Continue development of prof						-! D-::ma			
0:4- 01:#		, and waste, from the ASTs, Frac Tanks, Totes, and Drums. On-Scene Coordinator: ERRS Response Manager							
TXD 008950461					·				
	Contract Number: EP - S6 - 07 -02		Gary Moore, USEPA			LeRoy Cassidey, CB&I Federal			
Task Order: 062					Date: 3.10.2015		Time: 170)0	
PERSONNEL ON-SITE:	QTY	Used	Unused	EQUIPMENT ON- SITE:		QTY	USED	Unused	
Response Manager Foreman	1	1		Pick –up Tri	uck	3	3		
	1	1		Genera	ator	1	1		
	0	0		Trash Pun	nps	1	1		
Truck Driver/Equip Op	1	1			PID	1	1		
Laborer	2	2		Frac Tank w Li	ner	1	1		
Health and Safety Manager	0	0		4,000 PSI Pressure Washer		1	1	Contract Con	
PERSONNEL OFF-SITE				Open Top Roll	Off	8	8		
Subcontract Manager	1	1		Vacuum Truck Air Mo	ver	1	1		
Transport and Disposal Coord	1	1		Carbon Vapor U	Jnit	1	1		
Field Cost Accountant	1	1		Skid St	eer	1	1		
				Vacuum Box	xes	26	26		
				9,000 lb Overhead	Lift	1	1		
				Storage Tra	iler	1	1		
				Myers (Bean) Pu	mp	1	1		
				Air Compres	sor	1	1		

T&D Coordinator continued to work on manifest and LDR for current and upcoming waste shipments with Veolia ES and Republic Services. Continue to work with CB&I and TCEQ on disposal/treatment of waste. Checking suitability of quoted Totes and Drums.

Subcontract Administrator again requested Certificate of Insurance from JIT Distributing to set up vendor for tote, drum purchase.

The crew pumped water from the middle pond and South Pond areas. Crew prepared all VB and OT roll off for pick up by Republic Services. They completed transfer of materials from Group 4 Neutral Solids and Group 5 Organic Solids to VB 25343.

osc

. [] [][

ate: / / Tim

Date: 3.11.2015

Time:1130

Next OPERATIONAL PERIOD (administrative, tactical / resource status changes, special instructions, H&S)(Input for next DWO):

1200

Continue to pump water from the rain event. Continue solids removal from Group 21-26. Continue to cut up totes and drums and place pieces into OT 25337. Assist Lonestar with Overhead Lift Forklift.

Lonestar treatment and disposal of FT 1004 via TCEQ. Republic pick up of VB and Open Top Containers.

Continue to work with CB&I on TCEQ proposal for Clean Harbors and US Ecology. Continue preparations for material transfer for disposal of Groups 6-21.